To protect, promote & improve the health of all people in Florida through integrated state, county & community efforts.



Celeste Philip, MD, MPH

Surgeon General and Secretary

Vision: To be the Healthiest State in the Nation

# Questions and Answers ITB DOH16-056 Heating and Air Conditioning (HVAC) Maintenance

- Q1 I had a question on Filters for all locations and is there a filter list available.
- A1) Yes, please the below spreadsheet
- Q2) Quantity and type of VAV boxes in Tarpon Springs, Standard, and Fan Powered, reheat coils?
- A2) Pneumatic VAV boxes in Tarpon Springs, quantity unknown, style is unknown.
- Q3) Page 15 Item # 4 air handlers' pre-filters every two months and main filter every month?
- A3) Please see Addendum #1
- Q4) Is the previous contract available?
- A4) Yes, please see Order (ACB766) information below
- Q5) Who is the water treatment company you use or prefer for the chillers?
- A5) We do not have a treatment company. That is left to the contractor in this agreement.
- Q6) Confirm performing the preventative maintenance on all the equipment on the RFP?
- A6) Yes everything is on the list.
- Q7) Is the 2 chilled water loops and the Hot water loops part of the maintenance on the RFP?
- A7) Yes, refer to Attachment A (Specifications) 1<sup>st</sup> paragraph. I would consider that all the water loops are parts that would affect satisfactory operation of the units
- Q8) Are air handlers' pre-filters every two months and main filter every month as in the RFP?
- A8) Please refer to Q3
- Q9) What is your definition of monthly cleaning of evaporator coils and blower wheels is wiping and vacuuming them sufficient or do expect something more detailed?
- A9) Yes, wiping and vacuuming is sufficient.
- Q10) What is your definition of cleaning of the condenser coils of the chillers do you expect chemical to be applied and the power wash to be used monthly?
- A10) No, don't expect chemical to be applied Monthly please refer to Attachment A (Specifications)
- Q11) How many VAV boxes are there at each location?
- A11) This information is unknown
- Q12 Regarding service calls with there being unlimited, is the service call a billable service.
- A12) No the contract is for comprehensive service, limited only by the exceptions in Section A of the ITB. Repairs are included and you do not bill.



- Q13) Will we be allowed to go through each one of these units and provide a due diligence survey to make sure we're not assuming liability for the services not performed adequately by the previous contractor?
- A13 No. The new contractor will be responsible to service and maintain the system as it is.
- Q14) Will the award of this be based on Best Value?
- A14) The award will be made to the responsive and responsible vendor offering the lowest grand total.
- Q15) This is a full maintenance contract, no repairs will be paid outside of the contract?
- A15) Correct.
- Q16) With respect to the control system are they included in the maintenance section?
- A16) No they are not.

### **Equipment Spreadsheet**

### **Clearwater Center**

Identifier	Make	Model	Serial number	Man Date	Location	Туре	Filters	
AHU1-S	Johnson Controls	XTI-045X060-DAHA017A	CGYMXT0288	New 2013	Room 168	AHU	8-12x24x2	
AHU1-N	Johnson Controls	XTI-036X063-DAHA017A	CGYMXT087	New 2013	Room 142	AHU	8-12x24x2	
AHU2-S	Johnson Controls	XTI-042X089-DAJA017A	CGYMXT0292	New 2013	Room 210	AHU	6-20x20x2	
AHU2-N	Johnson Controls	XTI-042X060-DAH017A	CGYMXT0291	New 2013	Room 254	AHU	8-12x24x2	
Chiller S	Carrier	30RAP0505FA40100	1314Q50272	New 2014	Roof	CH	N/A	
Chiller N	Carrier	30RAP0405FA30100	1314Q50258	New 2014	Roof	CH	N/A	
Boiler	Burnham	4FW-78-45-60-PF	9582		Room 142	во	N/A	
Burner	Powerflame	C1-0-10(?)	39674525		Room 142	BU	N/A	
Elev Room	Mitsubishi	MU-A12WA-1	0002808T		Roof	CU	N/A	
Elev Room	Mitsubishi	MS-A12WA	1002753		Room 119	EVAP	integrated	
IT	Mitsubishi	MU-09NW2(?)	000586-T		Roof	CU	N/A	
IT	Mitsubishi	MS-09NW2	1001087		Room 238	EVAP	integrated	
Phone Room	No Info found	Water cooled			Room 254	EVAP	?	
Maintenance	LG	LW1214ER?	403TAQP06820		Room 145	Wall	integrated	
Lab	Frigidaire	unable to access			Room 124	Wall	integrated	

Center has 6 rooftop exhaust fans

Air handlers, chillers and thermostats operated by Johnson Controls / Metasys front end

Cold bank system

#### **Largo Center**

Identifier	Make	Model	Serial number	Man Date	Location	Туре	Filters
IT	Quietside	QSCE121	1210505-093604		South side	CU	N/A
IT	Quietside	QSCC121	1210505-093391		Room 138	EVAP	integrated
Conference <sup>1</sup>	Trane	TWH024B140F1	20364210	05/97	Room 112	Evap	1-20x20x1
Conference	Trane	TTR030C100A3	M235289AF	06/97	West side	CU	N/A
Dental	Sanyo	CL1872	0079004- 852213446-78002	10/10	East roof	CU	N/A
Dental	Sanyo	KS1872	098103- 8522134606000	07/10	Room 150	EVAP	integrated
AHU-1 <sup>3</sup>	Trane	2TEC3F30B1000A	6494L7K1V	12/06	Room 151	EVAP	1-20x20x1
CU-1	Trane	2TTB303A1000AA	7102SMR5F	03/07	East side	CU	N/A
AHU-2	Trane	TWE120E300AB	12324SJFBA	08/12	Room 151	EVAP	4-16x25x2
CU-2	Trane	TTA120E300AA	12364TKXYA	09/12	East side	CU	N/A
AHU-3 <sup>2</sup>	Trane	TWE18E300AA	16402T5CWA	10/16	Room 104	EVAP	
CU-3	Trane	TTA180H300AA	16365WJGTA	9/16	North side	CU	N/A
AHU-4	Rheem	RHGL-108ZL	F251401066	6/14	Room 141	EVAP	
CU-4	Rheem	RAWL-150CAZ	F451303504	11/13	South side	CU	N/A
AHU-5	Rheem	RHGL-180ZL	F411400006	10/14	Room 141	EVAP	
CU-5	Rheem	RAWL-150CAZ	7919F341304923	8/13	Room 141	CU	N/A

<sup>&</sup>lt;sup>1</sup>Conference AHU is ceiling mount (~10')

All units have electric heat

East roof has 2 rooftop exhaust fans

West roof has 3 rooftop exhaust fans and 1 inline exhaust fan with stack for room 123

Digital thermostats

<sup>&</sup>lt;sup>2</sup>AHU-3 has a condensate pump

<sup>&</sup>lt;sup>3</sup>AHU-1 is ceiling mount (~7')

#### **Mid County Center**

Identifier	Make	Model	Serial number	Man Date	Location	Туре	Filters	
AHU-1	McQuay	CAH032GDAM	FBOU110301980	Startup 1/24/12	Room 1400	AHU	4-12x24x2 4- 20x24x2 4- 24x24x2	
AHU-2	McQuay	CAH023GDAM	FBOU110301967	Startup 1/24/12	Room 1400	AHU	2-12x24x2 2- 20x24x2 4- 24x24x2	
AHU-3	McQuay	CAH027GDAM	FBOU110302044	Startup 1/24/12	Room 1400	AHU	3-12x24x2 3- 20x24x2 3- 24x24x2	
AHU-4	McQuay	CAH027GDAM	FBOU110302025	Startup 1/24/12	Room 1400	AHU	3-12x24x2 3- 20x24x2 3- 24x24x2	
AHU-5 <sup>1</sup>	McQuay	CAH005GDAM	FBOU110302026	Startup 1/24/12	Room 3005	AHU	2-20x24x2	
Chiller	McQuay	AWS210ADHEWNN- ER10	STNU110400060	Startup 1/24/12	NW corner	СН	N/A	
IT <sup>2</sup>	Mitsubishi	PLA-A36BA4	02A00527B	Startup 1/24/12	Room 1401	EVAP	integrated	
IT	Mitsubishi	PUY-A36NHA4	15U03143C	Startup 1/24/12	West side	CU	N/A	
Pump 1	Baldor	EM3313T	not found	Startup 1/24/12	Room 1400	Р	N/A	S
Pump 2	Baldor	EM3313T	not found	Startup 1/24/12	Room 1400	Р	N/A	S
VAV	Johnson Controls	SDREH	(55 units)	Startup 1/24/12		VAV	N/A	

<sup>6</sup> Inline exhaust fans

Chiller, air handlers, VAVs, exhaust fans and thermostats operated by Johnson Controls / Metasys front end

Air handlers, pumps and chiller, controlled by VFD's

55 VAVs for zone control, all have electric heat

All air handlers have cartridge filters to be replace bi-annually. Total count: 12-23% x11%x11½ All air handlers have UV lights - to be replaced annually 14-19%x23%x11½

<sup>1</sup>AHU5 is on second floor mezzanine (~10')

14-23%x23%x11½

<sup>2</sup>IT AHU is ceiling mounted (~8')

<sup>1</sup> duct blower kitchen exhaust - roof mount

#### **Pinellas Park Center**

Identifier	Make	Model	Serial number	Man Date	Location	Туре	Filters	$\perp$
AHU-1	Trane	BTE120B400EA	175308	S06	Room 029	EVAP	2-24X24X1	Ī
CU-1-1(A)	Trane	2TTA0048A3000AA	7302M6G3F	07/07	South side	CU	N/A	
CU-1-2(B)	Trane	2TTA0048A3000AA	725375E3F	06/07	South side	CU	N/A	
AHU-2	Trane	BTE120B400EA	175469	S07	Room 029	EVAP	2-24X24X1	
CU-2-1(A)	Trane	2TTA0048A3000A	725377N3F	06/07	South side	CU	N/A	
CU-2-2	Trane	2TTA0048A3000AA	7272PBR3F	07/07	South side	CU	N/A	
AHU-3	Trane	BWV180B300CA	180327	S12	Room 015	EVAP	6-20x25x2	
CU-3-1	Trane	TTA090A300FA	8173R5MAD	04/08	South side	CU	N/A	
CU-3-2	Trane	2TTA0060A3000AA	8164M5P4F	04/08	South side	CU	N/A	
AHU-4	Trane	BWV180B300CA	180328	S12	Room 015	EVAP	6-20x25x2	
CU-4-1	Trane	TTA090A300FA	8174KM6AD	04/08	South side	CU	N/A	
CU-4-2	Trane	2TTA0060A3000AA	8164M734F	04/08	South side	CU	N/A	
IT	Frigidaire	FFRE06L3Q18	KK52008526	05/15	Room 028	Wall	integrated	
Maintenance	Whirlpool	unable to access			Room 031	Wall	integrated	
Heat 1	Trane			'	Room 029		N/A	
Heat 2	Trane				Room 029		N/A	
Heat 3	Trane				Room 015		N/A	
Heat 4	Trane			'	Room 015		N/A	

6 inline exhaust fans

#### St Petersburg Center

Identifier	Make	Model	Serial number	Man Date	Location	Туре	Filters	
1N-1NW <sup>1</sup>	Trane	TWE090B300DA	224318FSH	08/02	Dental hall	EVAP	3-16X25X1	
1N-1NW	Trane	TTA120B300DA	2245CA3AD	06/02	Carport	CU	N/A	
1N-2NC	Trane	TWE090B300DA	2243LBE5H	6/02	Dental hall	EVAP	3-16x25x1	
1N-2NC	Trane	TTA090A300EA	224319YAD	08/02	Carport	CU	N/A	
1N-3NE⁴	Trane	TWE120D100AA	12014N7KBA	01/12	Room 1-110	EVAP	4-16x25x2	
1N-3NE	Trane	TTA120D300AA	12112RTTYA	03/12	Carport	CU	N/A	
1N-4S	Carrier	TWE180E300AA	J2717956	4/13	ADAP hall	EVAP	8-15x20x2	
1N-4S	Carrier	38AUZA07ADB5ADA0A0	J29198256	4/13	Carport	CU	N/A	
1S-1W <sup>3</sup>	Trane	TWE048C14FCO	P234UXN1V	06/99	Room 1-179	EVAP	1-20x20x1	
1S-1W	Trane	TTP048D100A0	R181N1T2F	04/99	South roof	CU	N/A	
1S-2NW	Trane	TWE240B300BB	J11180127	9/14	Room 1-243	EVAP	4-16X25X2 4- 16X20X2	
1S-2NW	Trane	TTA180B300AA	J17198703	9/14	South roof	CU	N/A	
1S-3NE	Trane	TWE240B300BC	J11180091	4/15	Room 1-243	EVAP	4-16X25X2 4- 16X20X2	
1S-3NE	Trane	TTA180B300BA	J15198079	04/94	South roof	CU	N/A	
1S-4TEL⁵	Carrier	FB4CNF036	0414A73359	01/14	Room 1-246	EVAP	1-16X20X1	
1S-4TEL	Carrier	24ABB336A610	0314E10496	01/14	South roof	CU	N/A	
2N-1NW	Trane	TWE120B300BB	J30170087	07/94	Room 2-156	EVAP	8-15x20x2	
2N-1NW	Trane	TTA120B300BA	J30198308	07/94	North roof	CU	N/A	
2N-2W	Trane	TWE180E300AA	12474NY0WA	01/12	Room 2-156	EVAP	8-15x20x2	
2N-2W	Trane	TTA180E300AA	13095MC7TA	03/13	North roof	CU	N/A	
2N-3E	Trane	TWE240B300BC	J11180099	11/15	Room 2-106	EVAP	4-16x25x2 4- 16X20X2	
2N-3E	Trane	TTA240B300BA	J31198765	07/94	Carport	CU	N/A	
2N-4SE	Carrier	40RUAA07A2A6AD	J04173039	2014	Room 2-106	EVAP	2-20x20x2	
2N-4SE	Carrier	38AUZA07A0B5A0A0A0	J29266462	2014	Carport	CU	N/A	
2S-1NE	Trane	THC120A3RGA0B84	817100953L	04/08	South roof	PKG	4-20X25X2	
2S-2SE	Trane	TSC120A3RGAA2NA	819191123L	05/08	South roof	PKG	4-20X25X2	
2S-3NW	Carrier	50TC-D12A2B5A0A0A0	40RUAA07A2A6ADA	04/94	South roof	PKG	3-20X20X2 3- 16X20X2	
2S-4SW	Trane	TSC120A3RGA2NA	819101129L	05/08	South roof	PKG	4-20X25X2	
2S-5W	Trane	THC092A3RCA2CA	817100957L	04/08	South roof	PKG	4-20x25x2	

### St Petersburg Center (Continued)

Identifier	Make	Model	Serial number	Man Date	Location	Туре	Filters	
identinei	IVIANG	Wodel	Serial Humber	Man Date	Location	турс	1 111.013	丄
3-1W	Trane	TWE120B300BB	J45172900	11/15	Room 3-128	EVAP	4-16x25x2	
3-1W	Trane	TTA180B300BA	T32198195	08/94	North roof	CU	N/A	
3-2WC	Trane	TWE120B300BB	J34170795	08/94	Room 3-127	EVAP	4-16x25x2	
3-2WC	Trane	TTA180B300BA	J08198357	02/94	North roof	CU	N/A	
3-3EC	Trane	TWE120B300BB	J40172091	09/94	Room 3-122	EVAP	4-16x25x2	
3-3EC	Trane	TTA180E300AA	11263MUETA	06/11	North roof	CU	N/A	
3-4E	Trane	TWE120B300BB	J34170798	08/94	Room 3-122	EVAP		
3-4E	Trane	TTA180B300BA	J42198905	10/94	North roof	CU	N/A	
4-1SE	Trane	TSC080A3R0A28A	817101010832		North roof	PKG	4-16x25x2	
4-2C	Trane	TSC120A3RGA2NA	817101248L	04/08	North roof	PKG	4-20X25X2	

4-3SW	Trane	TSC090A3RCA001C	8171087L	04/08	North roof	PKG	4-16x25x2	
4-4NW	Trane	TSC072E3R0A0	100911591L	03/10	North roof	PKG	4-16x25x2	
4-5NE	Trane	TSC090ER0A01	101511211L	04/10	North roof	PKG	4-16x25x2	
IT-E	Liebert	FH199AUAAM	306571-005	D-94	Battery room	EVAP	4-24X24X4 Roll poly	
IT-E	Liebert	CDF205A	C12L2F4815	L-2012	SE roof	CU	N/A	
IT-NE	Liebert	FH199AUAAM	306571-00?	D-94	Room 1-261	EVAP	4-24X24X4 Roll poly	
IT-NE	Liebert	CDF205A	054C81048	J-2005	SE roof	CU	N/A	
IT-NW	Liebert	FH199AUAAM	306571-00?	G-98	Room 1-264	EVAP	4-24X24X4 Roll poly	
IT-NW	Liebert	CDF205A	0611C85107	C-2006	SE roof	CU	N/A	
IT-S	Liebert	FH199AUAAM	306571-007		Room 1-256	EVAP	3-24X24X4 1- 20X24X4 Roll poly	
IT-S	Liebert	CDF205A	0037C37504	J-2000	SE roof	CU	N/A	

#### St Petersburg Center (Continued)

Identifier	Make	Model	Serial number	Man Date	Location	Туре	Filters	
Mail Room	Trane	TWE024C14FB0	1624BF2U	04/03	Room 1-115	EVAP	1-20x20x1	
Mail Room	Trane	2TTR1018A1000AA	31611JE5F	04/03	Carport	CU	N/A	
3 <sup>rd</sup> Floor IT	Mitsubishi	MS-A09WA	0002062	no date	Room 3-108	EVAP	integrated	
3 <sup>rd</sup> Floor IT	Mitsubishi	MU-A09WA	0003104	no date	South roof	CU	N/A	
Elev Room	LG	LG6014ER	402CXYQB4426		Elev room	Wall	integrated	
OA Unit	AAON	41794 RK-40-2-FO- 1F2:AAORGEODJ00MOB	200208-AKET07908	08/02	Carport	OA	10-20x25x2	
?	Trane	TWE180E300AA	12474Y0WA	01/12	Room 2-156	EVAP	8-15x20x2	

North roof has 3 rooftop exhaust fans

South roof has 5 rooftop exhaust fans

<sup>&</sup>lt;sup>1</sup>Unit 1N-1NW is ceiling mounted (~10')

<sup>&</sup>lt;sup>2</sup>ADAP Hall unit is ceiling mounted (~10') and has uv lights

<sup>&</sup>lt;sup>3</sup>Unit 1S-1W is ceiling mounted (~10') and has a condensate pump

<sup>&</sup>lt;sup>4</sup>Unit 1S-3NE has a condensate pump

<sup>&</sup>lt;sup>5</sup>Unit 1S-4TEL is ceiling mounted (~8")

### **Tarpon Springs Center**

Identifier	Make	Model	Serial number	Man Date	Location	Туре	Filters	
Medical	Carrier	FB4CNP060	1314A87334	2014		EVAP	1-20x20x1	
Medical	Carrier	224ABB360A340	1314E18882	2014	East side	CU	N/A	
Rooftop	Carrier	50TC-D28ABB5AOAOAO	1014P23851	2014	Roof	PKG	9-16X25X2	
IT	LG	LW1213ER	303CSFTA1819	2103		Wall	integrated	

<sup>1</sup> rooftop exhaust fan

<sup>6</sup> bath exhaust fans

#### ORDER NO. AF4D6B



### CHANGED: Order No. AF4D6B

Version Number: 3 Internal Version: false Issued on Mon, 13 Feb, 2017

Created on Mon, 13 Feb, 2017 by Ariba System

#### Supplier:

Johnson Controls, Inc. 3802 Sugar Palm Dr. Tampa, FL 33619 United States Phone: 1813-635-2219 Fax: 1813-635-2276 Contact: Ginger Fox

#### Ship to:

Florida Department of Health in Pinellas County 205 Dr ML King St N 3rd Floor St Petersburg, FL 33701 United States

#### Deliver To:

Patte Garrett

Distributors?: N Requester: Patte Garrett Ship To Code: A02eb2k8.q State Contract ID:

Contract ID: Requester Phone: PR No.: PR9534411-V3 MyGreenFlorida Content: N Shipping Method: Best Way FOB Code: INC-Dest

FOB Code Description: Destination freight paid by vendor and included in price. Title passes upon receipt. Vendor files any claims.

 $\underline{\text{Encumber Funds: Yes}}$ PO Start Date: Fri, 1 Jul, 2016 PO End Date: Fri, 30 Jun, 2017 Fiscal Year Indicator: 2017 PUI#: 6452 Site Code: 640000-52

Terms and Conditions: http://dms.myflorida.com/mfmp\_PO\_TC

P Card Order?: No

Item Action	Description	Part Number	Unit	Qty	Need By	Unit Price	Extended Amount
1 Modified	In accordance with ITB DOH13-075, Purchase		each	12	None	\$5,415.00000 USD	\$64,980.00000 USD

In accordance with ITB DOH13-075, Purchase order to cover the cost of A/C maintenance at the St. Pete, Pinellas Park, Largo, Clearwater, Tarpon Springs, and Mid County Health Centers as authorized by Tim Tate or designee and as per the terms and conditions of ITB# DOH13-075. This is the second year renewal of this ITB and this term is from July 1, 2016 through June 30, 2017.

Florida Department of Health, in Pinellas County

205 ML King St North

Rm 418

attn. accounts payable St Petersburg, FL 33701 United States

Entity Description: Department of Health Organization Code: 64365262400

Expai Exem	t Code: 0000 nsion Option: ption Status: ption Reasor	: NG No						
Buye	r Code:							
	Description	on						
Blar	ket Purchas	se Order						
1	ized Invoice							
Metho	od of Procure	ement: H - Agency ITB [s 287.057(1) (a), F.S.]						
Item	Action	Description	Part Number	Unit	Qty	Need By	Unit Price	<b>Extended Amount</b>
2	Modified	This is a line item to cover needed service calls.		each	1	None	\$1.00000 USD	\$1.00000 USD
	This is a lin	te item to cover needed service calls.						
205 M Rm 4 attn a St Pet	a Departmer IL King St N	ble						
Orgar Objec Expar Exem	Description nization Code t Code: 0000 nsion Option: ption Status: ption Reasor	: NG No						
Buye	r Code:							
	Description	on						
Blan	ket Purcha	se Order						
Item	ized Invoice	9						
Metho	od of Procure	ement: E - Purchase under \$2,500 [Rule 60A-1.002(2), F.A	A.C.]					

### **Changes**

- Purchase Order Total ordered changed from \$67,380.00000 USD to \$64,981.00000 USD
- Line Item 2, Accounting, Accounting 1, RoundedAmount changed from \$2,400.00000 USD to \$1.00000 USD
- Line Item 2, LI Amount Recorder in FLAIR changed from \$2,400.00000 USD to \$1.00000 USD
- Line Item 1, Accounting, Accounting 1, ERPTransactionDate changed from 09162016 to 02132017
- Line Item 1, ERPTransactionDate changed from 09162016 to 02132017
- Line Item 2, Accounting, Accounting 1, ERPTransactionDate changed from 09162016 to 02132017
- Line Item 2, Accounting, Accounting 1, PriorPeriodIndicator changed from (no value) to (no value)
- Line Item 2, ERPTransactionDate changed from 09162016 to 02132017
- Purchase Order TimeCreated changed from Fri, 16 Sep, 2016 to Mon, 13 Feb, 2017
- Line Item 2, Accounting, Accounting 1, CurrentFLAIRAmount changed from 2,400 to 1
- Line Item 2, Quantity changed from 2,400 to 1
- Purchase Order Total ordered changed from \$65,980.00000 USD to \$67,380.00000 USD
- Line Item 2, Accounting, Accounting 1, RoundedAmount changed from \$1,000.00000 USD to \$2,400.00000 USD
- Line Item 2, LI Amount Recorder in FLAIR changed from \$1,000.00000 USD to \$2,400.00000 USD
- Purchase Order Attachments 2 changed from [ariba.approvable.core.AttachmentWrapper [Baseld 82223206134 11rtknw6.d6 ]] to (no value)

\$64,981.00000

USD

**Total** 

- Line Item 1, Accounting, Accounting 1, ERPTransactionDate changed from 06202016 to 09162016
- Line Item 1, Accounting, Accounting 1, ERPMessage changed from SUCCESSFUL ENCUMBRANCE 60S to SUCCESSFUL ENCUMBRANCE 6SU

- Line Item 1, ERPTransactionDate changed from 06202016 to 09162016
- Line Item 2, Accounting, Accounting 1, ERPTransactionDate changed from 06202016 to 09162016
- Line Item 2, Accounting, Accounting 1, ERPMessage changed from SUCCESSFUL ENCUMBRANCE 60S to SUCCESSFUL ENCUMBRANCE 6SU
- Line Item 2, ERPTransactionDate changed from 06202016 to 09162016
- Purchase Order TimeCreated changed from Fri, 1 Jul, 2016 to Fri, 16 Sep, 2016
- Line Item 1, Accounting, Accounting 1, CurrentFLAIRAmount changed from 64,980 to 46,768
- Line Item 2, Accounting, Accounting 1, CurrentFLAIRAmount changed from 1,000 to 2,400
- Line Item 2, Quantity changed from 1,000 to 2,400

### **Attachments**

## **PRICE PAGE**

A Single Award Solicitation shall be made to the responsive, responsible Bidder offering the

lowest pric	e for ite	ms request	ted in	this ITB
-------------	-----------	------------	--------	----------

·	( ORiginal Bid)		OPTIONS FOR 3 YR Ren
Location	Monthly Price	Yearly price	Renewal Pricing (Optional)
205 Dr. M.L. King St. N St. Petersburg, FL 33701 Approx. 114,000 SF	\$ <u>1,650.25</u>	X 12 months = \$ 19,803.	1 <sup>st</sup> year renewal \$19,803. 2 <sup>nd</sup> year renewal \$20,298. 3 <sup>rd</sup> year renewal \$20,805.
6350 76 <sup>th</sup> Ave. N Pinellas Park, FL 33781 Approx. 14,000 SF	\$ <u>450.58</u>	X 12 months = \$ 5,407.	1 <sup>st</sup> year renewal \$ <u>5,407.</u> 2 <sup>nd</sup> year renewal \$ <u>5,542.</u> 3 <sup>rd</sup> year renewal \$ <u>5,680.</u>
310 N. Myrtle Ave. Clearwater, FL 34623 Approx. 25,000 SF	\$656.58	X 12 months = \$ 7,879.	1 <sup>st</sup> year renewal \$ <u>7,879.</u> 2 <sup>nd</sup> year renewal \$ <u>8,076.</u> 3 <sup>rd</sup> year renewal \$ <u>8,279.</u>
12420 130 <sup>th</sup> Ave. N. Largo, FL 33774 Approx. 17,000 SF	<b>\$460.66</b>	X 12 months = \$ 5,528.	1 <sup>st</sup> year renewal \$ <u>5,528.</u> 2 <sup>nd</sup> year renewal \$ <u>5,666.</u> 3 <sup>rd</sup> year renewal \$ <u>5,807.</u>
301 S. Disston Ave. Tarpon Springs, FL 34689 Approx. 13,000 SF	\$ <u>224.50</u>	X 12 months = \$ 2,694.	1 <sup>st</sup> year renewal \$_2,694. 2 <sup>nd</sup> year renewal \$_2,761. 3 <sup>rd</sup> year renewal \$_2,830.
8751 Ulmerton Road Largo, FL 33771 Approx. 54,280 SF	\$ <u>1,840.41</u>	X 12 months = \$ 22,085.	1 <sup>st</sup> year renewal \$_22,085 2 <sup>nd</sup> year renewal \$_22,637. 3 <sup>rd</sup> year renewal \$_23,203

Solicitation Number: DOH13-075

Invitation to Bid

Air Conditioning Maintenance